

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	9,6	37		and the second of the second of the second	
2	9,1	38			
3	9.1	36			
4	971	37			
1 2 3 4 5 6 7 8	9,6 9,1 9,1 9,1 9,3 9,3 9,3 9,3 9,3	37 36 37 36 37 39 38 40 40 37 41 38 47 50 39 41 41 45			
6	9,1	37			
7	9,3	39			
8	9,2	38			
9	9,3	40			
10	9.3	40			
11	9.3	37			
12	9.1	41			
13	9,1	38			
14	9.2	43			
15	9.1	47			
16	9,2	50			
10 11 12 13 14 15 16 17 18 19 20 21 22 23	9,1	39			
18	9.1	4/			
19	9,1	35			
20	9.2	39			
21	9,2	41			
22	9.3	45			
23	4.3	44			
24	9,2	42			
25	9,3	49		104	
26	9,3	41			
27	9.3	43	9		
28	9.3	40			
29	9.4	36			
30	9.1	38			
31	9,3	38			
(No =	N = Ex		n) <b>Tot</b> a	al N's	0

< <have< th=""><th>County: Hood River Agency: HOOD RIVER COUNTY</th></have<>	County: Hood River Agency: HOOD RIVER COUNTY					
minimums	ENTRY POINT					
been met for this day?	EP-A					
PWS ID 4100172						
CASCADE LOCKS, CITY OF						
Sample period: 8/23  Month/Year						

Number of excursions during this month: \_\_\_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference -		_				
Minimum Water Quality Parameter(s) as set by State:						
pH Alk	7.0 31.0	] (Alkalinity)				

Print Name: Sheldon Priez	
Signature: The Jam pura	
Date & Phone#: <u>∂</u> - 3 1 - 2 3	

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR\_97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/